

Germanium absolute efficiency calibration

Efficiency

10^{-3}
 8×10^{-4}
 7×10^{-4}
 6×10^{-4}
 5×10^{-4}
 4×10^{-4}
 3×10^{-4}
 2×10^{-4}
 10^{-4}

χ^2 / ndf

8.442 / 5

p0

0.06565 ± 0.009111

p1

-0.83 ± 0.02142

200

300

400

500

600

700

800

900

1000

E[keV]

